


... You can change what is shown on each symbol in Design Profit®

## Diagram Symbols

By default, **Actual Time** appears on symbols.



1. If you hold down the *Ctrl* and *Shift* keys on the keyboard and left click your mouse on the diagram, the symbols are **blank**.



2. If you do it again, the **Munro Lean Design® Score** will be shown.



3. Do it one more time, and you are back to **Actual Time**. Printouts of the diagrams will reflect this setting. PDF exports too!

This setting stays as long as you are running Design Profit® but is set back to Actual Time when you run it again.